

Appendix D Photos Baler frame

Top rail Channel steel



Opposite side view of top rail Channel steel



Bottom rail Channel steel



Bottom rail Channel steel



Bolts missing from floor plate



Housing for cylinder





Additional plate for support

