

## Boulder County Voluntary Oil and Gas Inspection Program - IR Camera Data

Boulder County facilities are primarily operated by the State's larger operators with a few smaller operators conducting business in the county as well. However, the large majority of facilities in Boulder County would fall under the one time AIMM inspection requirement.

Year	# Facilities Visited with IR Camera	# Facilities Found to Have a Leak or Venting Identified	Percentage with Leak or Venting Identified	Average Time Span For Repair
2014	128	53	41%	31 days
2015	75	33	44%	13 days
2016 (through August)	56	26	46%	18 days
<b>Totals</b>	259	112	43%	20 days (3 year average)

# Repair Confirmation Visits	Issues Unresolved	Issue Resolved	New Leak Identified	Percentage With New Leak Identified
44	3	41	12	27%

# Sites Visited in Multiple Years	# Sites Where a Leak is Detected in Multiple Years	% of Sites with Leaks Detected in Multiple Years
97	19	19%

Release Location Data	Tank	Separator	Wellhead	ECD	Pipeline	Flowline
2014	18	22	24	0	3	1
2015	18	13	10	3	1	0
2016 (through August)	12	10	7	5	0	0
<b>Totals</b>	48	45	41	8	4	1